

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	1	"20070043485"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/01 10:36
S2	62	(("7246113") or ("20050281256") or ("20060224485") or ("3555951") or ("3557351") or ("3568032") or ("3584269") or ("3589492") or ("3590340") or ("3590826") or ("3619126") or ("3631697") or ("3648132") or ("3656032") or ("3657653") or ("3665947") or ("3671885") or ("3694636") or ("3702945") or ("3702989") or ("3715575") or ("3717868") or ("3728582") or ("3754128") or ("3754629") or ("3761700") or ("3763384") or ("3767272") or ("3789206") or ("3795916") or ("3806658") or ("3824559") or ("3825304") or ("3826095") or ("3829652") or ("3838258") or ("3838889") or ("3843595") or ("3861263") or ("3875473") or ("3882740") or ("3903856") or ("3911682") or	OR	OFF	2008/10/01 10:38	

		("3914938") or ("3918257") or ("3923403") or ("3931502") or ("3947672") or ("RE28749") or ("3948486"),.PN.				
S5	21	meissner-peter.in.	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO	ADJ	ON	2008/10/01 10:40
S6	4	((("6175794") or ("3714627") or ("5387819")),.PN.	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO	OR	OFF	2008/10/07 11:42
S7	4	"6175794"	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO	ADJ	ON	2008/10/07 11:49
S8	29	"3714627"	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO	ADJ	ON	2008/10/07 11:52
S9	99	((("4531619") or ("5785347") or ("5951040") or ("5964478") or ("6076852") or ("6085151") or ("6087928") or ("6109648") or ("6203079") or ("6227565") or ("3656160") or ("4360308") or ("4408737") or ("4466214") or ("4500114") or ("4591678") or ("4781267") or ("4785907") or ("4811921") or ("4815889") or ("4887782") or ("4937692") or ("4945486") or ("4951069") or ("5226672") or ("5259574") or	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO	OR	OFF	2008/10/27 14:34

("5301902") or
("5335884") or
("5365850") or
("5382172") or
("5394326") or
("5411289") or
("5430649") or
("5431361") or
("5455726") or
("5468093") or
("5483447") or
("5484166") or
("5495156") or
("5503496") or
("5531290") or
("5538099") or
("5544915") or
("5547148") or
("5549410") or
("5556056") or
("5558300") or
("5566926") or
("5620202") or
("5664802") or
("5687279") or
("5707076") or
("5709405") or
("5718451") or
("5735435") or
("5737224") or
("5746395") or
("5749059") or
("5782479") or
("5787832") or
("5799974") or
("5818122") or
("5825098") or
("5825649") or
("5829782") or
("5835873") or
("5871232") or
("5899949") or
("5947514") or
("5964817") or
("5969599") or
("5969598") or
("5988676") or
("5995891") or
("5999871") or
("5997033") or
("6042145") or
("6046877") or
("6101062") or
("6116639") or

		("6130796") or ("6129168") or ("6140814") or ("6155385") or ("6157880") or ("6157881") or ("6158769") or ("6179516") or ("6181998") or ("6188940") or ("6196580") or ("6198387") or ("6203105") or ("6219605") or ("6219605") or ("6244571") or ("6245408") or ("6260879") or ("6279946") or ("6288636").PN.				
S10	15390	safety and impact and threshold	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO	ADJ	ON	2008/10/27 15:41
S11	1747	vehicle same (safety and impact and threshold)	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO	ADJ	ON	2008/10/27 15:41
S12	3991	vehicle same (safety and (impact or collision or contact or shock) and threshold)	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO	ADJ	ON	2008/10/27 15:42
S13	811	vehicle same (safety and (impact or collision or contact or shock) and threshold) and severity	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO	ADJ	ON	2008/10/27 15:42
S14	774	vehicle same (safety and (impact or collision or contact or shock) and threshold) and severity and (sensor or control unit)	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO	ADJ	ON	2008/10/27 15:43
S15	296	vehicle same (safety and (impact or collision or contact or shock) and threshold) and severity and (sensor or control unit) and reliability	US-PGPUB; USPAT; USOOR; FPRS; EPO; JPO	ADJ	ON	2008/10/27 15:43

S16	22	("3964016" "4836024" "5173614" "5446661" "5490069" "5540461" "5580084" "5609358" "5712784" "5748477" "5809439" "5868423" "5871232" "6003808" "6020812" "6031484" "6043736" "6125313"). PN, OR ("6312013"). URPN.	US-PGPUB; USPAT; USOCR	ADJ	ON	2008/10/27 16:45
S17	1	("2002/0169535").URPN.	USPAT	ADJ	ON	2008/10/27 17:15
S18	19	("3964016").URPN.	USPAT	ADJ	ON	2008/10/27 17:15
S19	11203	reliab\$5 and safety and impact and sensor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/27 18:34
S20	1376	reliab\$5 near6 sensor and safety and impact	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/27 18:34
S21	786	reliab\$5 near6 sensor and safety and impact and vehicle	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/27 18:35
S22	56	reliab\$5 near6 (sensor and safety and impact) same vehicle	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/27 18:35
S23	55	reliab\$5 near6 (sensor and safety and impact) and vehicle and threshold	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/27 18:52
S24	17	(reliab\$5 near6 (sensor and safety and impact) and vehicle and threshold) not breed.in.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/27 18:53
S25	257	701/46.cds.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 15:11

S26	72	701/46.ccls. and reliability	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 15:13
S27	5	701/46.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 16:10
S28	1728	701/45.ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 16:11
S29	53	701/45.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 16:11
S30	126	701/47.ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 16:28
S31	3	701/47.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 16:29
S32	39	701/35.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 16:30
S33	141	701/29-31.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:15
S34	86	701/29-31.ccls. and (monitor \$3 same reliability)and safety	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:15
S35	21	701/34.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:16

S36	0	180/232.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:21
S37	11	180/268.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:21
S38	17	180/271.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:23
S39	11	180/282.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:26
S40	0	180/283.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:30
S41	4	180/274.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:30
S42	0	180/281.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:52
S43	0	180/279.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:52
S44	24	700/30-33.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:52
S45	0	280/290.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:55

S46	0	280/304.3.ccls. and (monitor\$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:55
S47	0	280/304.4.ccls. and (monitor\$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:55
S48	0	280/727.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:55
S49	3	280/728.1.ccls. and (monitor\$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:56
S50	0	280/728.2.ccls. and (monitor\$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/30 17:57
S51	0	280/733.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 12:57
S52	6	280/734.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 12:57
S53	1	280/801.1.ccls. and (monitor\$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 12:59
S54	1	280/803-808.ccls. and (monitor\$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 12:59
S55	140	700/79-83.ccls. and (monitor\$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 13:00

S56	34	340/438.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 13:33
S57	0	137/522.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 13:39
S58	28	361/1.ccls. and (monitor \$3 same reliability)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 13:39
S60	6	airbag and safeing	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 13:43
S61	1408	airbag and calibrat\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 13:44
S62	55886	impact and classif\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 13:45
S63	5139	impact same classif\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 13:45
S64	789	impact same classify	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 13:45
S65	2	vehicle impact same classify	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 13:45
S66	167	vehicle impact same severity	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 13:48

S67	3035	history same impact	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 14:31
S68	6	history same impact severity	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 14:32
S69	161	history same impact same vehicle	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 14:32
S71	36	deterioration and lightning arrestor\$2	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 15:54
S72	4	(("7283901") or ("7236865") or ("6816766") or ("6836754")).PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	OR	OFF	2008/10/31 17:02
S73	20	"5387819"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 20:39
S74	458	replace and impact sensor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 21:03
S75	14	replace same impact sensor	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 21:03
S76	81	replace same firing circuit	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 21:08
S77	12	replace same firing circuit and vehicle	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 21:08

S78	336	replace same air bag	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 21:10
S79	53	replace near4 air bag	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/10/31 21:10
S80	1	("5580084").PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	OR	OFF	2008/11/01 23:08
S81	31	"5580084"	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/11/01 23:09
S82	3	behr-leonard-werner.in.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/11/02 00:33
S83	0	white-craig-william.in.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/11/02 00:37
S84	0	"white-craig-w.in."	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/11/02 00:37
S85	0	"white-craig.in."	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/11/02 00:37
S86	0	automotive systems laboratory.as.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	ADJ	ON	2008/11/02 00:37
S87	1	("4958851").PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	OR	OFF	2008/11/02 00:39

S88	1	("6647331").PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	OR	OFF	2008/11/05 23:24
S89	3	("6647331").URPN.	USPAT	ADJ	ON	2008/11/05 23:24
S90	1	("5424583").PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	OR	OFF	2008/11/06 00:42
S91	12	("5424583").URPN.	USPAT	ADJ	ON	2008/11/06 00:42
S92	1	("6175794").PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO	OR	OFF	2008/11/06 13:19

11/6/2008 3:01:08 PM

C:\ Documents and Settings\ lolsen\ My Documents\ EAST\ Workspaces\ 10553502 Meissner sensor failure.wsp